


OFFICER'S HOUSING TYPE 1D

Six examples exist: 2368, 2369, 2370, 2371, 2372, 2374.

These buildings were constructed in 1929 as Company Officers' Quarters. They are two story brick structures on concrete foundations with a hip roof over the main portion and a low slope roof over 14' x 9' side wing. The side wing is supported on concrete piers with wood lattice skirting between the piers. The original windows of the side wing have been replaced with vinyl double hungs.



1987 РНОТО

OFFICER'S HOUSING TYPE 1.D

CONDITION SURVEY DATA SHEET

	·//	A SOLVE STATE OF THE SECOND SE	AIC/	•	/&	BUILDING TYPE I-D REMARKS
EXTERIOR ELEMENT			/4			REMARKS
LANDSCAPING						
SIGNAGE						
DRAINAGE & GRADING	0 0		1			
LIGHTING PLANTING			-	1		
FOUNDATIONS						
CONCRETE WALL CONCRETE PIERS						
SKIRTING	\$ 6		8	3		ROTTING PEELING PAINT, MISSING GLATS
WALLS						
WOOD SIDING CONCRETE	0.0					
STUCCO				17 19		
CONCRETE/STONE FACE						
MASONRY PAINT				38.6		PAINT FAILURE
WOOD TRIM	FOR THE				1 1	PAINT FAILURE
STEEL COLUMNS						
METAL TRIM ASBESTOS SIDING	 					
ROOFS						
COMPOSITION						
BUILT-UP METAL	 3 4		+			
TILE	6 6					TREE DEBRIS AND MINOR MOSS
FLASHING	0 0					
ROOF ACCESSORIES BELL TOWER	╂╌┼╌┼		+			
CLERESTORY						
ATTIC VENTS						PEPAIUT .
GUTTERS SCUPPER BOXES	191 19		+	-		- Canada - C
DOWNSPOUTS	9 9					
MISC. PENETRATIONS	10					
DOORS WOOD PANEL	8 6	6.7			-	FLAT PANELS
FLUSH WOOD						
FLUSH METAL		6				
GLASS LIGHTS HARDWARE	28		1			
TRANSOM						
WOOD OVERHEAD METAL OVERHEAD	#		+		-	
WINDOWS						
WOOD DOUBLEHUNG	9 9	1.10	4			
WOOD CASEMENT GLASS BLOCK			+		-	
VINYL						
WOOD VENT/HOPPER	9 0	12.	 			
WOOD DECORATIVE WOOD FIXED		119-	+		 	
METAL CASEMENT						
METAL AWNING/HOPPER						
METAL DECORATIVE SCREENS/BARS	0 0		+_	 	 	ALUMINUM
PORCHES						
ROOFED	88		-			
ENCLOSED CONCRETE STEPS	8 8		1	-		MOSS, SPALLING
WOOD STEPS						
GRANITE STEPS	-		+			
BRICK PORCH & STEPS METAL RAILING	9 9		†		<u> </u>	
WOOD RAILING			1_			
COLUMNS	0 0		+	2	-	BASE JOINTS OPENING
ROOF BALUSTRADE FIRE ESCAPES	#		+	 	 	
METAL						
CHIMNEYS MASONRY	000		+_	4	-	CLEAN, REPORT, REPLACE BROKEN CORBELS
METAL			1			


OFFICER'S HOUSING TYPE 1D

CONDITION SURVEY

HIP ROOFED RESIDENCES

- 1. Shrubs and trees too close to wall. This will accelerate deterioration of walls and windows and clog gutters.
- 2. Columns exhibit water damage at bases. Mitered plinth joints are opening. Stave joints beginning to separate.
- 3. Paint is peeling from lattice skirting, portions in contact with soil are rotting, some slats are missing.
- 4. Chimneys are soiled and mortar is in bad condition. Some need to be rebuilt where corbelling has broken off.

MAINTENANCE AND REPAIR SCHEDULE



OFFICER'S HOUSING TYPE 1D

MAINTENANCE AND REPAIR NOTES

1. PLANTINGS

- a. Refer to article on "Planting and Pruning".
- b. Prune or remove shrubs and trees that are crowding building, or transplant to a location farther away from walls.

2. COLUMNS

- a. Refer to article on "Wood Columns". Do repair work only when wood has had sufficient time to thoroughly dry.
- b. Small cracks can be caulked or filled with standard wood filler.
- c. Opening joints should be reglued and clamped tight until glue has set.

3. LATTICE

- a. Lower grade beneath lattice such that lattice is not in contact with soil or "landscape bark".
- b. Replace rotted or missing slats.
- c. Scrape and sand areas of loose paint. Prime and paint.

4. CHIMNEYS

- a. Refer to article on "Chimneys".
- b. Clean masonry and scrape out all deteriorated mortar.
- c. Replicate original corbelling where existing has broken off or previously been removed.
- d. Match appearance, size, and color of original brick units and match color of mortar.